



BLUE SKY GENERAL SERVICES

Order Via Phone or Email: (647) 278-3838 / info@hvacbluesky.ca

Pick-Up at: 1100 Invicta Dr, Oakville, ON L6H 2K9, Unit 22

PARTS	DESCRIPTION	PRICE LOST LABOUR
	Honeywell 24/110 volts Actuator replacement	\$195 + TAX
	Honeywell Fan Coil Cartridge replacement	\$145 + TAX
	Actuator 24/110 Actuator replacement	\$325 + TAX
	Diverging two way valve replacement	\$195 + TAX
	110 volts universal Fan Coil motor \$365 plus Tax 220 volts universal Heat Pump motor \$599 plus Tax 1/6 Motor \$400 plus tax	\$285 + 35 + TAX
	110 volts universal Fan Coil motor \$365 plus Tax 220 volts universal Heat Pump motor \$599 plus Tax 1/6 Motor \$400 plus tax	+ TAX
	cage motor fan coil	\$225 + TAX
	Actuator replacement	\$320 + TAX
	Bathroom Exhaust Fan - Single Speed BB100	\$220+ TAX
	Bathroom Exhaust Fan - Single Speed B100	\$220 + TAX
	BATHROOM EXHAUST FAN - DUAL SPEED	\$465 + TAX
	Dryer Exhaust Booster Fan B300	\$425 + TAX
	DRYER EXHAUST BOOSTER FAN DK260	\$425 + TAX
	Lumo-X Flexible 6 Inch X 8FT Aluminum Air Duct for Dryer Vent Hose, Flexible Air Hose	\$120 + TAX
	Dryer Vent Cleaning The Service Includes the Following: Vent and Exhaust cleaning of all bathrooms Vent and Exhaust cleaning of dryer Cleaning dryer and the inner dryer Cleaning of lint trap and flexible duct (We provide lint traps on request)	\$300 + TAX

Order Via Phone or Email: (647) 278-3838 / info@hvacbluesky.ca

Pick-Up at: 1100 Invicta Dr, Oakville, ON L6H 2K9, Unit 22